Summary of Facility Information in the County of Golden Valley

Owner Name and Address: Fastgo Service 5 Highway 3 PO Box 128 Lavina MT 59046 Phone: (406) 636-4005

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
1913681	Fast Go Service	5 MT Highway 3	Lavina	59046	(406) 636-4005

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / S1 Currently in Use	3381	3/1/1996 10 / Ye	Gasoline 10,000	Unknown None	Flexible Plastic Double-Walled	Pressurized	B DEF BHIJKL	Yes Yes Yes Yes
2 / S2 Currently in Use	3382	3/1/1996 10 / Ye	Gasoline 10,000	Unknown None	Flexible Plastic Double-Walled	Pressurized	ABCDEFGH1J&L B DEF•H1JKL	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006

Summary of Facility Information in the County of Golden Valley

Owner Name and Address: Ryegate Public Schools 207 2nd Ave W PO Box 129 Ryegate MT 59074 Phone: (406) 568-2211

Sys Fac I	Location Name	Location Street Address	Location Ci	ty Zip	Location Phone	
1907975	Ryegate Public Schools Dist 1	207 2nd Ave W	Ryegate	59074	(406) 568-2211	

TankID/Alt TankID Status	Tag Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
2 / S2	1870 8/1/1996	Diesel	Asphalt Coated or Bare Steel	Flexible Plastic	Pressurized	ABCDEFGHIJ&L	Yes
Currently in Use	09 / Ye	5,000	None	Double-Walled		B DEF•HIJ&L	Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	Not Listed

Report Generation Date: 7/3/2006 Page 2 of 3

Summary of Facility Information in the County of Golden Valley

Owner Name and Address: Clifford Sutton 203 E Railway PO Box 170 Ryegate MT 59074 Phone: (406) 563-2378

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
1913735	Super D Grocery	203 E Railway Ave	Ryegate	59074	(406) 568-2378

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / S1 Currently in Use	3462	4/8/1996 10 / Ye	Gasoline 5,000	Unknown None	Flexible Plastic Double-Walled	Pressurized	ABC●EFGHIJKL B DEF●HIJKL	Yes Yes Yes Yes
2 / S2 Currently In Use	3727	12/1/1998 07 / Ye	Gasoline 8,000	Unknown None	Flexible Plastic Double-Walled	Pressurized	ABCOEFGHIJKU B DEFOHIJKU	Yes Yes Yes Yes
3 / S3 Currently In Use	3728	12/1/1998 07 / Ye	Diesel 4,000	Unknown None	Flexible Plastic Double-Walled	Pressurized	ABC®EFGHIJKL B DEF®HIJKL	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 3 of 3